U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NUMBER : 7,565,108 B2
DATED : July 21, 2009

INVENTORS · Sakari KOTOLA et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In Column 22

Claim 8, line 42, "wherein the processor of the second terminal responding terminal to the second terminal informs the Bluetooth module" should read, --wherein the processor of the second terminal responding to the first terminal informs the Bluetooth module--:

In Column 24

Claim 27, line 8, "Bluetooth page scan mode into after detecting" should read, --Bluetooth page scan mode after detecting--.

ADDRESS ASSOCIATED WITH CUSTOMER NUMBER: 85775

PATENT NO.

7.565.108 B2

No. of additional copies

 \Rightarrow 0

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burlow, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMIS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.